




PASSO




35 min




I


x2




II






III





IV




V



1




Cx6




M8x80 mm

Dx6




Ø10 mm

2




3




4

V

II




Cx2




M8x80 mm

Dx2




Ø10 mm




5

I




Cx2




M8x80 mm



Dx2





Ø10 mm








6



7



8



9

