





# PASSO




35 min




I




II






III





IV




V



1




**Cx6**




**M8x80 mm**

**Dx6**




**Ø10 mm**

2




3




4

V

II




Cx2




M8x80 mm

Dx2




Ø10 mm




5

I




Cx2




M8x80 mm



Dx2





Ø10 mm








6



7



8



9

