








120 min


TYP 601



$\pm 8 \times 30 \text{mm}$	$\pm 8 \times 60 \text{mm}$	$\pm 6 \times 42 \text{mm}$
		
A	A2	B2
64	2	12
$\pm 12/10 \text{mm}$	$L=20 \text{mm}$	$L=56 \text{mm}$
		
C5	D2	D4
12	28	2


±20  E11	±35/16mm  HG2	27/310mm  I4	±5/16mm  J3	±20/8mm  J14	±15/12mm  L	±12/10mm  L2	±10/8mm  L33	
6	6	6	16	12	30	18	2	
±6,3x13mm  L9	±6,3x20mm  M2	±6,3x20mm  M3	±10x50mm  O7	±3,5x13mm  P5	±3,0x20mm  P7	±4,0x16mm  R11	L=259mm  S	M4x9mm  U1
1	12	12	1	23	18	16	3	12

ISM-XIX-006



	Ersatzteil Nummer	Dimension
1/4	XIX.207 x2	1034x400x16
	XIX.404 x2	492x364x16
	XIX.301 x4	491x340x16
	XIX.616 x6	461x327x2,5
	WST.0156 x6	330x140x12
2/4	WST.0157 x6	330x140x12
	XIX.107	1633x399x16
	XIX.108	1633x399x16
	XIX.508	1633x365x16
	XIX.613 x2	1005x504x2,5
	XIX.614 x2	636x504x2,5






	Ersatzteil Nummer	Dimension
3/4	WST.0293 x6	450x140x12
	XIX.709 x3	996x206x16
	XIX.710	995x496x16
4/4	XIX.711	995x496x16
	F33 x4	




1

$\pm 12/10\text{mm}$  C5 12	$\pm 8 \times 30\text{mm}$  A 48
---	--

x6





2





x6

$\pm 6 \times 42\text{mm}$  B2 12
--










3

$L=20\text{mm}$  D2 12







x3

4










5

















x3

6

$\pm 8 \times 30 \text{mm}$  A 8	$\pm 15/12 \text{mm}$  C 8	$L=20 \text{mm}$  D2 4	$27/310 \text{mm}$  I4 3	$\pm 6,3 \times 13 \text{mm}$  M2 12
---	---	---	---	---









$\varnothing 8 \times 30 \text{ mm}$  A	$\varnothing 8 \times 60 \text{ mm}$  A2	$\varnothing 15 / 12 \text{ mm}$  C	$27 / 310 \text{ mm}$  I4	$\varnothing 6.3 \times 20 \text{ mm}$  M3	$\varnothing 20 / 8 \text{ mm}$  J14
8	2	12	3	12	12



8


L=130mm	4.0x16mm	L=20mm
		
F33	R11	D2
4	16	6







9

L=20mm




D2
6





10





11














12




13







		
L2	P7	L
18	18	18











$\pm 10 \times 50 \text{mm}$ O7 1	$\pm 3.5 \times 13 \text{mm}$ L9 1	$\pm 3.5 \times 13 \text{mm}$ P5 1
--	---	---




16






M4x9mm  U1 12	L=259mm  S 3	±3.5x13mm  P5 6
--	---	--








17





±5/16mm  J3 16	±20  E11 6
--	--



		
†35/16mm	†3.5x13mm	
HG2	P5	L33
6	12	2





 2	 4
+3.5x13mm	

