











# ADEMO 3







| No | T(mm) | L(mm) | w(mm) | pcs. |
|----|-------|-------|-------|------|
| 1  | 16    | 1468  | 387   | 1    |
| 2  | 16    | 1468  | 357   | 1    |
| 3  | 16    | 765   | 405   | 1    |
| 4  | 16    | 765   | 405   | 1    |
| 5  | 16    | 683   | 357   | 1    |
| 6  | 16    | 1468  | 116   | 1    |
| 7  | 18    | 230   | 730   | 3    |
| 8  | 18    | 230   | 730   | 3    |
| 9  | 16    | 350   | 140   | 6    |
| 10 | 16    | 350   | 140   | 6    |
| 11 | 16    | 668   | 140   | 6    |
| 12 | 3     | 681   | 347   | 6    |
| 13 | 3     | 1477  | 350   | 1    |
| 14 | 3     | 1477  | 350   | 1    |



1



2



3

M1

2


M1

x2


4

Diagram 4 illustrates the mounting of the sliding door system to the side panel. The diagram shows three sliding door units being attached to a side panel using screws E2 and M1. A circular callout labeled '3' indicates the previous step. A detailed inset shows the correct alignment of the door unit with the panel. Two small diagrams show the correct and incorrect way to insert the M1 screw. A legend in the top right corner identifies the screws: E2 (6,3x13, x6) and M1 (x6).


5




6





7





8




9




10




11




12




13







14




15



x3

|                                                                                   |                                                                                    |                                                                                    |                                                                                    |
|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|
| F                                                                                 | M1                                                                                 | K                                                                                  | M                                                                                  |
|  |  |  |  |
| 7x50                                                                              |                                                                                    | 8x30                                                                               |                                                                                    |
| x2                                                                                | x4                                                                                 | x6                                                                                 | x4                                                                                 |



16

