
















K30  30	T1  24	M1  24	ZRA  2	KS  4
STB  8	M25  4	W4x16  6	Z1  24	PS  9
PZ  2	UM  4	KF50  6	Q  1	





H200






K30  4	M1  4
T1  2	E5x13  6
PS  4	









W4x16  4	ZRA  2	K30  4	M1  4
---	---	---	--



K30  18	M1  12	T1  12	E5x13  12	RP  6	Q  1	KF50  6
---	--	--	---	---	--	---





M25



4

UM




4

STB




8

A=B



90°



A=B

