





90 min



TYP 802






					
E13	O	SX17	SS6	R2	U16
4	1	2	2	10	4





									
A	B2	C	C5	D2	E	HG2	I4	J3	J44
28	6	16	6	22	6	2	3	4	6
									
L	L1	L9	L46	M2	M8	O7	P5	P7	U1
22	1	1	4	6	6	1	13	6	6

ISM-OZM-004







	Ersatzteil Nummer	Dimension
	OZM.107	732x499x16
	OZM.108	732x499x16
	OZM.505	716x458x16
	OZM.705 x3	240x506x16
	OZM.706	671x490x18
	OZM.203	1038x500x16
	OZM.404	1004x481x16
	OZM.904	494x120x16
	OZM.905	494x70x16
	OZM.301	493x420x16
	OZM.607 x2	1013x361x2,5
	OZM.608 x3	455x327x2,5
	WST.0183 x3	330x100x12
	WST.0184 x3	330x100x12
	WST.0338 x3	444x100x12








1 — 18




1 — 5
19 — 31

1


$\pm 12/10\text{mm}$  C5 6	$\pm 8 \times 30\text{mm}$  A 12
--	--



x3





2




$\pm 6 \times 42\text{mm}$  B2 6

x3




3








$L=20\text{mm}$  D2 6
--







x3






















4




5















$\pm 8 \times 30 \text{mm}$  A 12	$\pm 15/12 \text{mm}$  C 12	$L=20 \text{mm}$  D2 8	$27/310 \text{mm}$  I4 3	$\pm 20/16 \text{mm}$  J44 6	$\pm 6,3 \times 13 \text{mm}$  M2 6	$\pm 6,3 \times 28 \text{mm}$  M8 6	$\pm 3,5 \times 13 \text{mm}$  P5 4
 L46 2							





7



$\varnothing 8 \times 30 \text{ mm}$  A	$\varnothing 15/12 \text{ mm}$  C	$L = 20 \text{ mm}$  D2	 L46	$\varnothing 3.5 \times 13 \text{ mm}$  P5
4	4	8	2	4







8




9













10







11













$\pm 3.0 \times 20 \text{mm}$  P7 6	 L 16	L=1002mm  L1 1
--	---	--






48x15cm  SX17 2	L=96cm  SS6 2	M5,8x30mm  U16 4	4.0x30mm  R2 10	 O 1	14  E13 4
---	---	--	---	---	---










$\pm 10 \times 50 \text{ mm}$  O7 1	 L9 1	$\pm 3.5 \times 13 \text{ mm}$  P5 1
---	--	--



15





16







17


 $\pm 35/16\text{mm}$	 $\pm 3.5 \times 13\text{mm}$
HG2	P5
2	4


















18













$\pm 8 \times 30 \text{mm}$  A	$\pm 15/12 \text{mm}$  C	L=20mm  D2	27/310mm  I4	$\pm 20/16 \text{mm}$  J44	$\pm 6,3 \times 13 \text{mm}$  M2	$\pm 6,3 \times 28 \text{mm}$  M8	$\pm 3,5 \times 13 \text{mm}$  P5
12	12	8	3	6	6	6	4




L46
2






$\varnothing 8 \times 30 \text{ mm}$  A	$\varnothing 15/12 \text{ mm}$  C	$L = 20 \text{ mm}$  D2	 L46	$\varnothing 3.5 \times 13 \text{ mm}$  P5
4	4	8	2	4







21




22













23








24













$\pm 3.0 \times 20 \text{mm}$  P7 6	 L 16	L=1002mm  L1 1
--	---	--





					
E13	SX17	SS6	U16	R2	O
4	2	2	4	10	1









$\varnothing 10 \times 50 \text{ mm}$  O7 1	 L9 1	$\varnothing 3.5 \times 13 \text{ mm}$  P5 1
---	--	--



±5/16mm  J3	4
--	---





M4x9mm  U1	 E
6	6



30

 HG2 2	 P5 4
--	---



31

