















±8x30mm	±6x42mm	±15/12mm	±12/10mm					
								
A	B2	C	C5					
20	2	12	2					
L=20mm	±20	27/310mm		±6,3x13mm	±3.5x13mm	±4.0x16mm	L=59mm	M4x9mm
								
D2	E11	I4	L	M2	P5	R11	S	U1
14	4	1	6	4	2	16	1	2





	Ersatzteil Nummer	Dimension
	XIX.109	434x399x16
	XIX.110	434x399x16
	XIX.208 x2	434x400x16
	XIX.404	400x364x16
	XIX.617	443x409x2,5
	XIX.619	377x327x2,5
	WST.0156	330x140x12
	WST.0157	330x140x12
	WST.0295	366x140x12
	XIX.712	396x275x16
	 F33 x4	



XIX.405








XIX.208-G




XIX.619

1



$\pm 12/10\text{mm}$  C5 2	$\pm 8 \times 30\text{mm}$  A 8
--	---



2





$\pm 6 \times 42\text{mm}$  B2 2











3





$L=20\text{mm}$  D2 2
--



4





5





6

$\pm 8 \times 30 \text{mm}$  A	$\pm 15/12 \text{mm}$  C	$L=20 \text{mm}$  D2	$27/310 \text{mm}$  I4	$\pm 6,3 \times 13 \text{mm}$  M2
12	12	4	1	4









7

$L=20 \text{mm}$  D2
4




8




L=130mm	4.0x16mm	L=20mm
		
F33	R11	D2
4	16	4





9









10




11



12



13



L=59mm	±3.5x13mm	M4x9mm	±20
1	2	2	4

