



90 min

TYP 601





 A	 A2	 B	 C	 D2	 D4	 E1	 HG2
24	7	14	31	23	4	10	5
 J3	 K4	 K48	 L	 L9	 L46	 O	
12	2	7	14	1	2	1	

 SX15	 SS9
2	2
 U16	 E13
4	4
 R2	
14	


 O7	 P5	 P7	 U
1	27	4	14















ISM-OZM-009



	Ersatzteil Nummer	Dimension		Ersatzteil Nummer	Dimension
				OZM.209	831x398x16
1/3	OZM.118	284x397x16	2/3	OZM.412	814x381x16
	OZM.512	268x325x16		OZM.910	814x70x16
	OZM.208	521x400x16		OZM.911	268x814x16
	OZM.411	488x381x16		OZM.912	1349x830x16
	OZM.413	488x337x16		OZM.913	829x245x16
	OZM.302 x3	487x320x16	3/3	OZM.713	223x810x18
	OZM.909	488x70x16		OZM.117	1634x399x16
				OZM.511	1634x399x16
				OZM.617	1627x497x2,5
				OZM.715	1573x484x19














1

$\varnothing 8 \times 30 \text{ mm}$  A	$\varnothing 15/12 \text{ mm}$  C	$L = 20 \text{ mm}$  D2	 L46	$\varnothing 3.5 \times 13 \text{ mm}$  P5
14	12	10	1	2





2




A 10	C 16	D2 10
--	--	---









3








4



5




6




7

6,4 x 50mm







B






O

2



1




8




9






38x15cm	L=128cm	M5,8x30mm	14
			
SX15	SS9	U16	E13
2	2	4	4




12

$\pm 4.0 \times 30 \text{ mm}$ R2 14	 O 1
---	-------------------








13


$\pm 15/12 \text{ mm}$ C 3











14




$6,4 \times 50 \text{ mm}$ B 4	 O 1	 K48 7	$M4 \times 22 \text{ mm}$ U 14
---	-------------------	---------------------	---













±8x60mm	L=20mm	6,4 x 50mm	
A2	D2	B	O
3	3	4	1










$\varnothing 3.0 \times 20 \text{ mm}$ P7 4	 L 14
--	--------------------















10x50mm O7 1	L9 1	3.5x13mm P5 1
-----------------------------------	--------------------	------------------------------------





 L46	$\varnothing 3.5 \times 13 \text{ mm}$  P5	$\varnothing 5 / 16 \text{ mm}$  J3	$\varnothing 20$  E11
1	2	12	10



$\varnothing 35 / 16 \text{ mm}$  HG2	$\varnothing 3.5 \times 13 \text{ mm}$  P5	 K4
5	16	2

