






















K30  42	T1  32	M1  36	X  36	STB  6	UM  3	K1  2
KF  6	W4x16  4	MF  4	SM  4	E5x13  24	M22  3	A1  2
Q  1	W3x16  4	ZP  2	PZ  2	4.0x30  1	ZM  4	






 RP 3	 E5x13 6	 T1 8
--	---	--




					
RP	PZ	T1	E5x13	M1	K30
3	2	8	6	8	4








		
T1	M1	K30
2	4	4










M1  12	K30  16	MF  4
K30		
T1  2		




ZP	W4x16
	
2	4



M1	K30	T1	E5x13	KF	Q	RL
						
12	18	12	12	6	1	6





















2








2







STB	SM	W3x13	ZM
6	4	3	3



 M22	X 	UM 
3	36	3

