











|                 |          |          |                   |           |                    |             |
|-----------------|----------|----------|-------------------|-----------|--------------------|-------------|
| K30<br>46       | T1<br>30 | M1<br>32 | x<br>32           | STB<br>12 | SM<br>5            | J<br>8      |
| 5x9<br>F1<br>32 | KF<br>32 | Q<br>1   | 4.0x30<br>H<br>10 | GW<br>10  | 3,5x16<br>F3<br>32 | L<br>R<br>8 |
| K45<br>1        | T2<br>1  |          |                   |           |                    |             |

|                                                                                  |                                                                                  |                                                                                    |                                                                                    |                                                                                    |                                                                                    |
|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|
|  |  |  |  |  |  |
| 8                                                                                | 8                                                                                | 16                                                                                 | 4                                                                                  | 4                                                                                  | 14                                                                                 |





|    |     |     |   |
|----|-----|-----|---|
| M1 | K30 | 5x9 | L |
|    |     |     |   |
| 4  | 4   | 12  | 3 |



|        |   |    |    |     |    |
|--------|---|----|----|-----|----|
| 3,5x16 | Q | KF | M1 | K30 | T1 |
|        |   |    |    |     |    |
| 32     | 1 | 32 | 16 | 32  | 16 |

